Safety Performance Metrics

December 2009 With Quarterly Comparisons

Safety Performance Metrics December 2009

	OSHA Recordable (YTD)	2009 Limit Rate	OSHA Recordable Rate	OSHA Lost Time (YTD)	2009 Limit Rate	OSHA Lost Time Rate	PVA (YTD)	PVA Rate	MVA (YTD)	2009 Limit Rate	MVA Rate
District	105	5.5	5.5	15	0.8	0.8	47	7.1	32	8.0	4.8
Corporate Services	1	0.0	(1.1)	0	0.0	0.0	0	0.0	0	0.0	0.0
Customer Services	26	6.4	5.6	4	0.6	0.9	10	7.9	8	12.0	6.3
Distribution Services	57	8.7	9.7	9	1.9	1.5	25	7.0	14	7.8	3.9
Energy Supply	7	4.0	2.6	0	0.3	0.0	7	6.0	7	4.1	5.2
Internal Services	12	4.1	3.5	2	0.0	0.6	5	10.7	3	13.1	6.4
Technology	2	8.0	1.2	0	0.0	0.0	0	0.0	0	0.0	0.0

OSHA Recordable Rate:	# of Recordable Cases x 200,00				
	Total number of hours worked				
Lost Time Rate:	# of Lost-time Cases x 200,000				
	Total number of hours worked				
Motor Vehicle Accident (MVA) Rate : Accidents that exceed \$750 in damage	# of Accidents* x 1,000,000				
Accidents that exceed \$750 in damage	Total number of miles driven				


SD-6 Safety Metrics







2009 District Safety Performance - Final

		OCUA	0000	OCUA		0000			1		0000	
		OSHA	2009 Limit	OSHA	OCUL	2009 Limit	05118 1				2009 Limit	
		Recordable	Rate	Recordable	OSHA	Rate	OSHA Lost	D1 4 8			5 .	
Cost Center		Count		Rate	Lost Time		Time Rate	PVA	PVA Rate	MVA		MVA Rate
SMUD District Total		105	5.5	5.5	15	0.8	0.8	47	7.1	32	8	4.8
Corporate Services		1	0	1.1	0	0	0.0	0	0.0	0	0	0
CC 737 Legislative & Reg		26		5.7	0		0.0	0	0.0	0		0
	Customer Services		6.4	5.6	4	0.6	0.9	10	7.9	8	12	6.3
CC 503	Cust Lead & Bus Svs	1		3.2	0		0.0	0	0	0		0
CC 506	Financial Services	3		5.6	1		1.9	0	0	0		0
CC 508	Field Services	13		12.9	3		3.0	9	8.5	7		6.6
CC 510	Sales & Service	4		3.5	0		0.0	0	0	0		0
CC 522	Strategic Operations	1		3.1	0		0.0	0	0	0		0
CC 540	Comm & Community Rel	3		8.1	0		0.0	0	0	0		0
CC 560	Programs & Services	1		1.1	0		0.0	1	7.2	1		7.2
Distribution S	Distribution Services		8.7	9.7	9	1.9	1.5	25	7.0	14	7.8	3.9
CC 877	COE Business Tech	3		5.4	0		0.0	1	Х	0		0
CC 886	COE Design	4		3.0	0		0.0	1	2.8	0		0
CC 887	COE Work Performance	50		13.8	9		2.5	23	7.5	14		4.6
Energy Suppl	у	7	4	2.6	0	0.3	0.0	7	6.0	6	4.1	5.2
CC 460	Generation Design	0		0	0		0.0	2	12.0	2		12.0
CC 461	Generation Maint	4		5.3	0		0.0	5	5.4	4		4.3
CC 464	RS Nuclear Oper Fuel	1		9.3	0		0.0	0	0	0	///	0
CC 465	RS Indus Decommissing	1		9.4	0		0.0	0	0	0		0
CC 728	Systems Ops & Reliab	1		1.4	0		0.0	0	0	0		0.0
Internal Servi	ices	12	4.1	3.5	2	0	0.6	5	10.7	3	13.1	6.4
CC 336	Transportation	1		3.4	1		3.4	0	0	0		0
CC 338	Facilities	6		7.4	0		0.0	3	22.6	3	////	22.6
CC 339	Rancho Seco Park	1		13.4	1		13.4	1	42.2	0		0
CC 340	Supply Chain Svcs	1		2.1	0		0.0	0	0	0	///	0
CC 344	Security Operations	1		2.3	0		0.0	1	6.1	0	4/4/	0
CC 644	Controller & Acctg	2		4.0	0		0.0	0	х	0		х
Business Technology		2	0.8	1.2	0	0	0.0	0	0	0	0	0
CC 375 Tech Resource Center		2		1.2	0		0.0	0	0	0		0







December Injury Summary

		<u> </u>
(3) SOFT TISSUE INJURIES – Cumulative		
Related Work Task/Cause	Occupation	Work Group
Work Station Usage Not specified Not specified	Office Tech Sr. Office Specialist	Communications & Advertising Credit
Field Work Blowing leaves	Utility Worker	Facilities Maintenance
(1) SOFT TISSUE INJURIES – Acute		
Related Work Task/Cause	Occupation	Work Group
Field Work Not specified	Lineman – Appr	Distribution Services
(3) Abrasion, Puncture, Cut or Contusion		
Related Work Task/Cause	Occupation	Work Group
Field Work Removing meter Closing meter cabinet Removing meter seal	Lineman Sr. Meter Reader Meter Tech	Distribution Services Field Services Distribution Services
(1) Trauma		
Field Work Cutting chain with bolt cutters	Cust Svcs Field Rep	Customer Services



Serious Safety Incidents

December

December 10 - CS

Field Rep was cutting chain with bolt cutters and metal hit eye

December 10 - DS

Lineman removing meter cover cut hand and forearm.



December Vehicle Accident Summary

Business Unit	Туре	Cause	MVA	PVA
Field Services	Collision with vehicle moving in same direction	Driver distraction - cell phone, eating, etc.	Y	Y
Work Performance	Other - non-collision	Bumper made contact with ground while vehicle was descending from embankment at top of hil	N	N
	Backing into object or vehicle	Failure to leave sufficient room	Υ	Υ
	Backing into object or vehicle	Other	Υ	Υ
Facilities	Running into/sideswiping object at roadside	Failure to leave sufficient room	Y	Υ
Security	Running into/sideswiping object at roadside	Failure to leave sufficient room	N	Υ

DEPARTMENT	2006 LIMIT	2006 ACTUALS	2007 LIMIT	2007 ACTUALS	2008 LIMIT	2008 ACTUALS	2009 LIMIT	2009 ACTUALS
DISTRICT								
RECORDABLE	124	136	112	154	123	113	112	105
LOST TIME	36	22	33	24	17	24	16	15
MVA'S	*N/A	78	*N/A	67	71	37	66	32
CORPORATE SERVICES								
RECORDABLE	0	0	0	1	0	0	0	1
LOST TIME	0	0	0	0	0	0	0	0
MVA'S	*N/A	0	*N/A	0	0	0	0	0
CUSTOMER SERVICE								
RECORDABLE	45	37	41	46	35	29	33	26
LOST TIME	10	5	9	7	4	3	3	4
MVA'S	*N/A	22	*N/A	24	20	8	18	8
DISTRIBUTION SERVICES	DISTRIBUTION SERVICES							
RECORDABLE	52	68	47	71	62	56	56	57
LOST TIME	18	14	17	10	12	12	12	9
MVA'S	*N/A	42	*N/A	34	39	19	36	14
ENERGY SUPPLY								
RECORDABLE	7	12	6	16	11	8	10	7
LOST TIME	3	1	2	4	1	0	1	0
MVA'S	*N/A	7	*N/A	4	6	3	6	6
INTERNAL SERVICES								
RECORDABLE	16	18	14	16	13	19	12	12
LOST TIME	5	2	4	2	0	9	0	2
MVA'S	*N/A	7	*N/A	4	6	7	6	3
BUSINESS TECHNOLOGY								
RECORDABLE	2	1	2	4	2	1	1	2
LOST TIME	0	0	0	1	0	0	0	0
MVA'S	*N/A	0	*N/A	1	0	0	0	0



